

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Permanent Building.

Deepthi - H  
M.G.M Central School  
Kodumon, padbanambhitta Dist.  
1) 3 x 32.35m x 17.1m x 3.6m (B.C.C roof)  
2) 2 x 29.03m x 8.21m x 3.6m (R.C.C roof)  
3) 1 x 29.03m x 9.71m x 3.6m (R.C.C roof)

5. Period for which the certificate is issued
6. Nature of defects, if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

2023 - 2024

Nil

No

Yes


The structure is sound for conducting classes under normal weather condition.



Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE


certified that the school building was inspected by me on 26/07/2023 and found to be fit / unfit to conduct classes for the period 2023 - 2024 for the reasons stated above.

Place : Kodumon  
Date : 26/7/2023

  
SMITHA RAJ  
500/8-6-13 PRINCIPAL  
MGM CENTRAL SCHOOL  
KODUMON - 691 555



Manager  
M. G. M. Central School  
Kodumon

  
26/7/23  
Assistant Engineer  
Assistant Engineer  
LID & EW Section  
Kodumon Grama Panchayath